

REBOUNDER® MOUNTING INSTRUCTIONS

with Straight Shot Attachment for John Deere 750 Drills

Before working on your planter or drill

DANGER: When storing or working on the drill always install cylinder stops or place the drill on stands to prevent personal injury or damage to the attachments.

WARNING: Do not roll back or back up the drill in or on the ground as this can result in damage to the Rebounder.



PLEASE: Read instructions completely and verify all package contents before beginning installation.

Straight Shot Rebounder for JD Drills

PART # ORSSK

Package Contents (per single row)

Item	Quantity
Straight Shot Rebounder with molded-in 1/4" to 1/8" QC2	1
1/4" Black Hose	1
1/4" x 7/8" Whiz Bolt.	1
Instruction Sheet	1



Step #1:

Remove the 1/4" bolt and washer holding the seed flapper in place on the seed boot of the JD drill.

Now you are ready to mount the Rebounder in the place where the John Deere seed flapper was.

Step #2:

Place the Rebounder in the bottom of the seed boot.

Raise the press wheel and let it rest on the square tab. Place the 1/4" x 7/8" whiz bolt through the Rebounder and tighten it into place.



Step #3:

Insert one end of the black hose into the top end of the Straight Shot's Quick Coupler.

